

Bluetooth Update Instructions For AVIC-F900BT, AVIC-F700BT

NOTES:

- ✓ **This information is designed to work exclusively with AVIC-F900BT and AVIC-F700BT sold in Europe, including Russia.**
- ✓ The update is for AVIC-F900BT and AVIC-F700BT with the original map data as for units which have been updated with CNSD-100FM.
- ✓ If you have any difficulty carrying out these instructions, please first refer to the Firmware Update FAQ included in this document and/or contact Pioneer Customer Support Center.
- ✓ This software update improves Bluetooth connectivity **for Blackberry phones only.**

A. Check the current Bluetooth Software version of the Navigation Unit:

- Switch on your Navigation unit by switching on the ignition of your car. If you don't see "Top Menu" displayed on top of the display, press the "menu" button to open top menu.
- Press "Phone" and "Phone Settings" to open Phone Settings menu.
- Make sure "Bluetooth On/Off" is set to "On".
- Scroll down the menu by pressing the downward arrow on the left.
- Select "Bluetooth Software Update"
- You should see the screen like below :



If the version displayed is SW330 or higher, then your product is equipped with the software which has improved compatibility with Blackberry and there is no need for any upgrade.

B. Download the Bluetooth update file from Pioneer's website:

Download the required Bluetooth update file from the website to your computer:

For Blackberry users (Version 3.30): "**AVIC_Fseries BT330.zip**"

For Non-Blackberry users (Version 2.90): "**Pioneer AVIC F series BT290.zip**"

C. After the copying process is completed, confirm the file size:

Check the file size of the downloaded Bluetooth software file by right-clicking on the file and selecting Properties. (Download again if the file size is incorrect)

AVIC_Fseries BT330.zip: 370 KB (379.439 bytes)

Pioneer AVIC F series BT290.zip: 373 KB (382.039 bytes)

D. Decompress the file:

Once you have downloaded the file to your computer, locate the file on your hard disk drive and double click the file to decompress it. (If you do not have a decompression utility installed on your computer, you can easily download one for free.)

E. Create the Update SD-card (updating is not possible using USB connection or CD):

To create an update SD-card, you will need:

- A PC with SD-card reader/writer
- One formatted blank SD-card with minimum capacity of 512 MB
- Supported OS: Windows: 98, 98SE, Me, 2000, XP, Vista, MacOS

Put the SD-card in the SD-card reader/writer.

Copy the unzipped 3 files to the root directory of an empty SD-card.

for version 3.30: "CK5000_330_RLS.bin", flash_p4_lwp.bin", rtl_115200_8192_p4.bin"

for version 2.90: "CK5000_290_RLS.bin", flash_p4_lwp.bin", rtl_115200_8192_p4.bin"

F. Update the Bluetooth Software for your unit:

Turn the ignition on.

- Press "Phone" and "Phone Settings" in the main menu to open Phone Settings menu.
- Put the SD-card which contains the update files into the unit
- Make sure "Bluetooth On/Off" is set to "On".
- Scroll down the menu by pressing the downward arrow on the left.
- Select "Bluetooth Software Update"
- Press "Software Update" button on screen to start updating.
- Update takes about 3 minutes.

Note: Do not turn off or disconnect the power, or remove the SD card while the updating is in progress. When the upgrade is completely finished the message "Software has been updated" will be displayed.

- Turn off the ignition from your car / demo board
- Remove the SD card from the set

The upgrade was successful if the Version (see point 1) has become SW330.
The Bluetooth software of your unit is updated.

Firmware Update FAQ

Q: What if my set shows "n/a" on Bluetooth software version information?

A: Please press "Software Update" button again on Bluetooth Software Update screen to retry the process.

Q: What if the set switches off while updating software?

A: Turn off the ignition key and turn on again. Then perform the whole procedure on point 6.

Q: What if I cannot upgrade my set / the set does not show the start up screen after more than 1 attempt?

A: Please contact your local Pioneer service organisation for a product check-up.

Contact Information

Pioneer Customer Support Center

<http://www.pioneer.eu>

Copyright(c) 2009 Pioneer Corporation